


# Structural / Seismic Review



HCG performed a structural review and assessment of a retail property in San Francisco. The client had several concerns that were major factors in their prospective purchase of the building.

The client wanted to know important information that only a structural engineer could provide. Our score included was an onsite structural inspection, plan and zoning review through the San Francisco Building Department, seismic investigation and other analysis. HCG's report gave the client the needed information which determined current state and future possibilities for the structure.

***“HCG reviews property for structural integrity, zoning, seismic hazards, and future build-out possibilities”***

*Solution*

*Structural review and assessment*

*Location*

San Francisco, CA